The Ease of Synergy SPC Software Setup Provides Rapid Implementation



# Synergy SPC Software Setup and Implementation

### Software Install (Estimated time: 15-20 min.)

With Synergy SPC software you have the option to install on a server or locally on workstations. If the software is installed on the server, just simply create a shortcut to the applicable exe file(s). No client install is required. Since the software is a flat file system, minimal if any IT support will be needed. To install the software simply place the CD into the workstation and follow the setup screens.

### File Organization

The first thing to consider before creating any files is how to best organize your data files for easy access. You can create as many folders and subfolders needed to facilitate navigation by operators to locate data files.

### **Critical Characteristics**

You need to determine what specific data you will be collecting and if your focus will be on product or process. You will need to determine which type of Control Chart will best fit your needs, your sample size or subgroup and your customer specifications.

File Creation (Estimated time: 2-3 min. for each characteristic)

### To create data files:

- 1. Launch either the Synergy 1000 or Synergy 2000 Engineer Level.
  - Create Data Bank & Data Table Data Bank Name: Lower Data Table Nam Chart Type Upper Nominal 0.000 Xbar and R 0.000 Xbar and R 0.000 0.000 0.000 0.000 Xbar and R 0.000 0.000 -Xbar and B 0.000 0.000 0.000 4 Xbar and R 0.000 0.000 0.000 5 Xbar and R 0.000 0.000 0.000 6 • 0.000 Xbar and R • 0.000 0.000 Xbar and R 0.000 0.000 0.000 • 8 176 Current Folder: C:\Synergy2000 9.0 Create Select Folder... Templates... Cancel
- 2. From the File menu select Create Data Bank and Data Tables.

3. A notification window opens reminding you to select the file folder where you want your data files saved. Click OK.

Syne	ergy2000Engineer
	minder: Please verify current folder location before entering Data nk/Data Table information. To change folder location click 'Select Folder'.
	ОК

4. Click Select Folder to navigate to the file folder in which your data files will be stored. Click OK.

Data	Bank Name:	E	Browse for Folder	<b>x</b>			
	Data Table Name	De	Browsing		Upper	Nominal	Lower
1			E Desktop		0.000	0.000	0.000
2			Network	Ţ	0.000	0.000	0.000
3		_	District Libraries	Ţ	0.000	0.000	0.000
4		_	Interpreter      Inter     Interpreter     Interpreter     Interpreter      Interprete	=	0.000	0.000	0.000
5		_	Local Disk (C:)	Ē	0.000	0.000	0.000
6		_	DVD RW Drive (D:) goldmine (\zontec-spc) (G:)		0.000	0.000	0.000
-		_	Shared (\ZONTEC-SPC) (I:)	- F	0.000	0.000	0.000
7			You have selected the folder				
8			C:\Synergy2000 9.0		0.000	0.000	0.000
							. 13
			OK Can	el			

- 5. Enter Data Bank Name (product or process)
- 6. Enter Data Table Name (characteristic being monitored)
- 7. Enter Data Table Description (should at least contain Data Table Name)
- 8. Select Chart Type (Xbar & R, Xbar & S, Median & R)
- 9. Select Sample Size (1-25 \*sample size can vary per characteristic)
- 10. Select Decimal (0-6 how many decimal places you will be measuring out to)
- 11. Enter specification limits (Upper, Nominal, Lower)
- 12. Repeat steps 6-11 for additional characteristics.

	Data Table Name	Description	Chart Type		Samp	le Size	Decimal	Upper	Nominal	Lower	Ŀ
1	Head Diameter	Head Diameter PN1234	Xbar and R	+	5		4 +	0.7640	0.7520	0.7400	ſ
2	Flange Thickness	Flange Thickness PN1234	Xbar and R	+	3	-	3 🕌	0.145	0.135	0.125	1
3	Weight	Weight PN1234	Xbar and R		5		2 .	1.27	1.25	1.23	1
4			Xbar and R		1		3 .	0.000	0.000	0.000	
5			Xbar and R		1	-	3.	0.000	0.000	0.000	ł
6			Xbar and B	-	1	-	3 🗸	0.000	0.000	0.000	ł
7			Xbar and R	-	1	-	3 🗸	0.000	0.000	0.000	ł
8			Xbar and B	+	1	-	3 🗸	0.000	0.000	0.000	ł
				-			. –			.1.	ł

- 13. Click Create.
- 14. A notification window opens verifying you want to create the files. Click Yes.

Synergy20	00Engineer	3 3	x			
Are you sure you want to create this new Data Bank and associated Data Tables?						
	[	<u>Y</u> es <u>N</u> o				

15. Your files are created and data entry can begin.



Rapid implementation is a key benefit of Synergy SPC software. In just 30-45 minutes you can begin monitoring and then start controlling, evaluating and analyzing a process. This application not only offers powerful SPC features, but is also easy to use. Synergy workshops, a 1-day training course, are available in-house at our Cincinnati, OH location or on-site at your facility. On-line training options are also available in 45 min modules.

## About Zontec

Since 1983, Zontec has been providing statistical process control (SPC) software to industry-leading companies across the globe. Zontec is highly respected for its continued focus on innovation and for constantly integrating new technologies that help businesses address quality issues, strive for long-term continuous improvement, and maximize profitability. Zontec is unique in the industry by offering a full suite of products to meet the needs of companies of all sizes. Committed to an aggressive product development schedule, Zontec software is created, tested, documented and totally supported within the company without outsourcing. This gives Zontec complete control over product development of our products. If a service agreement customer decides to upgrade to the next level of the Zontec product suite they can do so at minimal cost through our 100% Investment Retention program. They will be able to access all their previous data in the new product, minimizing production interruption. Zontec software has been adopted worldwide by more than 5,000 companies, spanning virtually every industrial category.



© 2014 Zontec Inc. All rights reserved www.zontec-spc.com